
Stereo-Lithography

- Advantages
 - No machining skill
 - No miscommunication
 - "Impossible" parts / assemblies
 - Fast (prototyping)
- Disadvantages
 - Material limitations
 - Cost
 - Slow (mass production)

Stereo-Lithography

- How does it work?
 - Stacked 2-D "images"
 - Printing in air
 - Build (model) material
 - Support material
 - Why should you care?
 - You keep model material
 - You throw away support material
 - You PAY for both

\$37.00 4 Hours



\$24.00 2½ Hours





Things You Can Make

- Durable working parts
 - Joints
 - Gears
 - Captive Assemblies
 - Intricate parts
 - Miniature parts
- Flexible parts
 - Snaps



Resources

ece Dectrical an Computer Engineering

Dr. Leo J. Stocco, BASc, PhD, PEng

- https://download.ece.ubc.ca
 - SolidWorks
 - Objet Studio
- ece.ubc.ca/~leos

SolidWorks help 3-D Printing help

- Design guidelines
- Tutorials / Examples
- Documentation
- FAQ

Important Specs

• Min. feature width: 1mm

• Min. feature width (sturdy) : 2mm

• Min. joint gap: 0.2mm

• Cost: 1\$ per gram (build + support)

Caveats

- Large STL files
 - Spherical features
 - Small angle spec in STL generator
 - Keep STL file < 100MB
- Joints not easily freed
 - Large joint surface area
 - Coupled joints
 - Small (fragile) shafts
 - Glossy welds

Fasteners

- Pressed Splines
- Screws
 - Machine vs sheet metal
- Retaining Rings
 - Internal
 - External
- Cotter Pins
- Flexible Snaps
- Crazy Glue

Ordering Parts

- A quota must be set up by your instructor BEFORE you place your order. Price is \$1 per gram (build + support material).
- Send email to help@ece.ubc.ca
- Subject Line
 - 3D Printing (Course Number)
- Specify
 - Which group you are ordering parts forOrder
 - Number of parts (refer to each .stl file)
 - Material (standard or flexible)
 - Special instructions (matte finish, printing orientation, etc.)
- Attach all associated .stl files
- Pick up parts in MCLD 112B when you receive an email that your parts are ready.

Post-Processing

